To: Vann, Bradley[Vann.Bradley@epa.gov]

From: Kessler, Martin

Sent: Tue 12/29/2015 3:42:32 PM

Subject: RE: Final version of the Bridgeton Brush Fire Response Report

Hey, no problem. Ben sends 'em, I post 'em!

From: Vann, Bradley

Sent: Tuesday, December 29, 2015 9:41 AM

To: Kessler, Martin < Kessler.Martin@epa.gov>; Mahler, Tom < mahler.tom@epa.gov> **Cc:** Washburn, Ben < washburn.ben@epa.gov>; Brees, Angela < Brees.Angela@epa.gov>

Subject: RE: Final version of the Bridgeton Brush Fire Response Report

You rock! Thanks Martin.

Bradley Vann - Remedial Project Manager

U.S. Environmental Protection Agency

Superfund Division

Missouri/Kansas Remedial Branch

11201 Renner Blvd.

Lenexa, KS 66219

Phone: 913-551-7611

Fax: 913-551-9611

Cell: 816-714-0331

From: Kessler, Martin

Sent: Tuesday, December 29, 2015 9:40 AM **To:** Mahler, Tom mahler.tom@epa.gov>

Cc: Washburn, Ben < washburn.ben@epa.gov >; Vann, Bradley < Vann.Bradley@epa.gov >;

Brees, Angela < Brees. Angela@epa.gov>

Sub	iect:	RE:	Final	version	of the	Bridgeton	Brush	Fire Res	ponse Rep	port

Already posted at http://www3.epa.gov/region07/cleanup/west_lake_landfill/pdf/bridgeton-surface-fire-emergency-response.PDF

From: Mahler, Tom

Sent: Monday, December 28, 2015 10:31 AM

To: Kessler, Martin < Kessler.Martin@epa.gov >; Brees, Angela < Brees.Angela@epa.gov > Cc: Washburn, Ben < washburn.ben@epa.gov >; Vann, Bradley < Vann.Bradley@epa.gov >

Subject: Final version of the Bridgeton Brush Fire Response Report

I believe it's time to think about getting this document posted to the West Lake Landfill webpage.

Just as a reminder, this report describes the response that EPA conducted immediately following a grass fire that occurred on the West Lake Landfill complex but not on OU-1, Area 1 or Area 2. This report includes the results of the soil samples collected on or near the burned area.

One additional note, this document will be part of the administrative record for the Surface Fire Mitigation removal action which was signed about 2 weeks ago.

Let me know if there are any questions.

Tom Mahler

x7416